

AD-A170 796

CULTURAL RESOURCES INVENTORY OF THE MONTZ FRESHWATER
DIVERSION PROJECT CO. (U) GOODWIN (R CHRISTOPHER) AND
ASSOCIATES INC NEW ORLEANS LA W A FRANKS ET AL.

1/3


UNCLASSIFIED

23 JUN 86 COELMN/PD-86-06-UOL-2

F/G 5/6

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A170 796



**US Army Corps
of Engineers**
New Orleans District

CULTURAL RESOURCES SERIES
Report Number: COELMN/PD-86-06

2

**CULTURAL RESOURCES INVENTORY OF
THE MONTZ FRESHWATER DIVERSION
PROJECT CORRIDOR, ST. CHARLES PARISH,
LOUISIANA VOLUME II**

Final Report

June 23, 1986

**R. Christopher Goodwin and Associates, Inc.
1306 Burdette Street
New Orleans, Louisiana 70118**

**DTIC
ELECTE
AUG 11 1986
S D**

DISTRIBUTION STATEMENT A
Approved for public release
Distribution Unlimited

**Prepared for
U.S. Army Corps of Engineers
New Orleans District
P.O. Box 60267
New Orleans, LA 70160-0267**

Unclassified. Distribution is unlimited.

DTIC FILE COPY

86 8 8 092

ADA170796

**CULTURAL RESOURCES INVENTORY OF THE MONTZ FRESHWATER
DIVERSION PROJECT CORRIDOR, ST. CHARLES PARISH, LOUISIANA**

Volume II

By

**Herschel A. Franks, Jill-Karen Yakubik, Jeffrey E. Treffinger,
R. Christopher Goodwin, Paul C. Armstrong**

June 23, 1986


**Prepared for Department of the Army, New Orleans District, Corps of
Engineer, P. O. Box 60267, New Orleans, Louisiana 70160, Under
Delivery Order No. 14, Contract DACW29-84-0029.**

D-

**R. Christopher Goodwin and Associates, Inc.
1306 Burdette Street
New Orleans, Louisiana 70118**

TABLE OF CONTENTS
APPENDIX III
HISTORIC STANDING STRUCTURE SURVEY FORMS

Montz 1.....	6
Montz 2.....	9
Montz 3.....	12
Montz 4.....	15
Montz 5.....	19
Montz 6.....	22
Montz 7.....	25
Montz 8.....	28
Montz 9.....	31
Montz 10.....	34
Montz 11.....	37
Montz 12.....	40
Montz 13.....	43
Montz 14.....	46
Montz 15.....	49
Montz 16.....	52
Montz 17.....	55
Montz 18.....	58
Montz 19.....	62
Montz 20.....	65
Montz 21.....	68
Montz 22.....	71
Montz 23.....	74



Distribution	
Availability Codes	
Dist	Avail and/or Special
A-1	

Montz 24.....	77
Montz 25.....	80
Montz 26.....	83
Montz 27.....	86
Montz 28.....	89
Montz 29.....	92
Montz 30.....	95
Montz 31.....	98
Montz 32.....	101
Montz 33.....	104
Montz 34.....	107
Montz 35.....	110
Montz 36.....	113
Montz 37.....	116
Montz 38.....	119
Montz 39.....	122
Montz 40.....	125
Montz 41.....	128
Montz 42.....	131
Montz 43.....	134
Montz 44.....	137
Montz 45.....	140
Montz 46.....	143
Montz 47.....	146
Montz 48.....	149

Montz 49.....	152
Montz 50.....	155
Montz 51.....	158
Montz 52.....	161
Montz 53.....	164
Montz 54.....	167
Montz 55.....	170
Montz 56.....	173
Montz 57.....	176
Montz 58.....	179
Montz 59.....	182
Montz 60.....	186
Montz 61.....	189
Montz 62.....	192
Montz 63.....	195
Montz 64.....	198
Montz 65.....	201
Montz 66.....	204
Montz 67.....	207
Montz 68.....	210
Montz 69.....	213
Montz 70.....	216
Montz 71.....	219
Montz 72.....	222

Montz 73.....225

Montz 74.....228

HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 1986

Film Type: Tri-Pan-X

Roll Number: Roll 6

Frame Number(s): 24, 25, 26

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 1

Parish: St. Charles

Address: 1736 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace, LA

Size: 1:24,000

UTM 332240 N 74580 E

Sect. 11 T 12S R 7E

Remarks: not eligible for National Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: A front gabled bungalow with attached gables at the west and south. There is a screened porch at the front (west). The house is sheathed with beveled, 1"x 8" lapped boards. The roof is sheathed with tin and there are exposed rafters at the eaves. Windows are original 6 over 6 wooden double hung. A skirt of corrugated metal is present at the base. The house is surrounded by a very old post and mesh fence.



Condition of the Building

Good

Length—front-back

27'-0" feet

Width—side-side

23'-6" feet

Orientation—bearing from

Front West

Roof inclination

degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (X) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #1

View from the East



View from the Southwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 1986
Film Type: Tri-Pan-X
Roll Number: Roll 6
Frame Number(s): 26, 28, 29
Location of Negative: _____
R.Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 2
Parish: St. Charles
Address: 1739 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace, LA
Size: 1:24,000
UTM 332240 N 74580 E
Sect. 11 T 12S R 7E
Remarks: not eligible for National Register
National Register Status: Not listed

Social Information

Resident: _____
Ownership Information: _____
Name: _____
Address: 1739 Union Lane
Town: Montz, LA
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 2 is a mobile home which is oriented north south. This trailer is shored with concrete blocks and shimmed with wood; it is secured with augered stakes and galvanized straps. A television aerial as well as a grape arbor are present at the eastern side.



Condition of the Building

Good
11'-9" feet
Width—side-side
56'-0" feet
Orientation—bearing from
Front West
Roof inclination
degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

Documents seen by you and bearing on the structure:

Title

Date Location

Experts who advised you specifically on this structure:

Name and Address

Name and Address

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____


City: _____

Historic function of principal building: (X) residential () religious
() social () commercial () industrial () governmental
() agricultural () other _____

Historic structures (dependencies) present on the same site: () store
() kitchen () quarters () garconierre () office () barn
() corncrib () smokehouse () shed () privy () cistern
() fence () wall () well () machinery () cemetery
() notable garden () pigeonierre () gazebo () statuary () mill
() garage () commissary () other _____

Montz #2

View from the Northwest



View from the South



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 1986
Film Type: Tri-Pan-X
Roll Number: Roll 6
Frame Number(s): 30,31
Location of Negative: _____
R.Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 3
Parish: St. Charles
Address: 1740 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace, LA
Size: 1:24,000
UTM 332040 N 745260 E
Sect. 11 T 12S R 7E
Remarks: not eligible for National Register
National Register Status: Not listed

Social Information

Resident: _____
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: A side gable two crib cabin type with a front gable attachment added over the entrance. This house is raised on concrete blocks and is sheathed with 1"x 8" lapped weatherboards; all window frames are aluminum and modern. A carport at the northern side appears to be a recent addition. At the (east) of the house there is a concrete slab which is currently not in use.

Condition of the Building



Excellent
Length—front-back
24'-4" feet
Width—side-side
53'-10" feet
Orientation—bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonnier () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #3

View from the North



View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 6

Frame Number(s): 32, 33, 34

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 4

Parish: St. Charles

Address: 1742 Union Lane

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3322000 N 745260 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Mrs. Eugene

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 4 is a creole cabin raised on both brick and concrete piers. Cypress weathboards are present beneath modern asphalt shingles; window frames are both aluminum and wooden framed. The roof is a side gable with an attached shed at the rear; rafters are exposed and the roof is tin. Although the core of the structure is old, there is little historical integrity.



Condition of the Building

Poor _____

Length—front-back _____

42'3" feet

Width—side-side _____

28' feet

Orientation—bearing from _____

Front West _____

Roof inclination _____

degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary (☒) other trailer

Montz #4

View from the North



View from the South



Montz #4

Trailor to the North



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 1
Frame Number(s): 1, 2, 3
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 5
Parish: St. Charles
Address: 1740 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321960 N 745260 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Mrs. Alma
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: This structure is a bungalow raised on pre-poured concrete pillars and concrete blocks. Imitation brick sheathing is under 1" by 18" asphalt shingles. Two over aluminum windows are present. The roof is a ft. gable with attached gable over the porch. There are exposed rafters at the eaves.



Condition of the Building

Good _____
Length—front-back _____
34'8" feet
Width—side-side _____
24'3" feet
Orientation—bearing from _____
Front West
Roof inclination _____
degree _____
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (X) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonnier () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #5

View from the Northwest



View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 1

Frame Number(s): 4, 5, 6

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 6

Parish: St. Charles

Address: 1749 Union Lane

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321920 N 745240 4 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Michele Hines

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: This structure is a single story ranch raised on concrete blocks. Sheathing is lapped masonite weather boards. The windows are aluminum framed. The roof is hipped with an attached hip over the entrance, roofed with seal tab shingles. There is a 16" soffit surrounding the structure.



Condition of the Building

Good

Length—front-back

38'2" feet

Width—side-side

42'3" feet

Orientation—bearing from

Front West

Roof Inclination

degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconnerie () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #6

View from the South



View from the West



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 1
Frame Number(s): 7, 8, 9
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 7
Parish: St. Charles
Address: 1751 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321880 N 745240 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: _____
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession


First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: This structure is a side gable cabin, with an attached gable at the entrance and a hipped 2-story addition, the original structure being raised on concrete pillars, the addition is on a slab. The original house is sheathed with lapped masonite weatherboards, the addition is concrete block on the bottom and aluminum siding on the second story. There is a shed at the northern side.

Condition of the Building

Good _____
Length—front-back _____
57'0" feet
Width—side-side _____
37'0" feet
Orientation—bearing from _____
Front West
Roof inclination _____
degree
Operator _____



Montz #7

View from the Northwest



View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 1
Frame Number(s): 13, 14, 15
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 8
Parish: St. Charles
Address: 1752 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321820 N 745220 E
Sect. 11 T 1S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Maryetta Victor
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 8 is a shotgun which is raised on concrete block piers. The sides are sheathed with asphalt shingles beneath which are horizontal cypress boards; the windows are wood frames. The roof is a front gable with exposed at the eaves and is sheathed with tin. A gable addition is present at the northern side.



Condition of the Building

Poor _____
Length—front-back _____
52'10" feet
Width—side-side _____
14'7" feet
Orientation—bearing from _____
Front West
Roof inclination _____
degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #8

View from the Northwest



View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 1
Frame Number(s): 13, 14, 15
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 9
Parish: St. Charles
Address: 1753 Union St.
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321800 N 745220 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: _____
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: This structure is a ranch raised on concrete blocks. Sheathing is 6" lapped weatherboards and the windows are aluminum framed. The roof is hipped. There is a vented soffit around the house. It has a slate roof with hip tiles. There is a carport on the northern side.



Condition of the Building

Good
Length—front-back
34'2" feet
Width—side-side
24' feet
Orientation—bearing from
Front East
Roof Inclination
_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (☒) shed () privy () cistern
 () fence () wall () wall () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #9

View from the Southwest



View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information
Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle
Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 1
Frame Number(s): 23, 24
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information
Parish Number: _____ Site: Montz 10
Parish: St. Charles
Address: 1754 Union
Montz, LA
Topographic Quadrangle
Name: LaPlace
Size: 1:24,000
UTM 3321780 N 745220 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information
Resident: _____
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession
First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property: _____
Architectural and historical significance: Site 10 is a mobile home which is raised on metal jacks. An entrance is present on the western side with steps leading to it. There is a shell lot present in front of the trailer.



Condition of the Building
Fair
Length—front-back
66'0" feet
Width—side-side
13'10" feet
Orientation—bearing from
Front West
Roof Inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Historic function of principal building: (☒) residential (☐) religious
 (☐) social (☐) commercial (☐) industrial (☐) governmental
 (☐) agricultural (☐) other _____

Historic structures (dependencies) present on the same site: (☐) store
 (☐) kitchen (☐) quarters (☐) garconierre (☐) office (☐) barn
 (☐) corncrib (☐) smokehouse (☐) shed (☐) privy (☐) cistern
 (☐) fence (☐) wall (☐) well (☐) machinery (☐) cemetery
 (☐) notable garden (☐) pigeonnier (☐) gazebo (☐) statuary (☐) mill
 (☐) garage (☐) commissary (☐) other _____

Montz #10

View from the East



View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information
Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle
Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 2
Frame Number(s): 1, 2, 3, 4
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information
Parish Number: _____ Site: Montz 11
Parish: St. Charles
Address: _____
Montz, LA

Topographic Quadrangle
Name: LaPlace
Size: 1:24,000
UTM 3321780 N 745200 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information
Resident: _____
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession
First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property: _____
Architectural and historical significance: Site 11 is a shotgun which stands on brick and concrete piers. Vertical cypress boards are present beneath the lapped weather boards; windows are original and wooden. The roof is hipped with exposed rafters at the eaves, the roof is tin. A gable attachment is present at the northern side; there is also a shed on site.



Condition of the Building
Poor
Length—front-back
46'2" feet
Width—side-side
14'4" feet
Orientation—bearing from
Front West
Roof Inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (☒) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #11

View from the East



View from the Southwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1970
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 2
Frame Number(s): 5, 6, 7
Location of Negative: R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 12
Parish: St. Charles
Address: 1730 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321720 N 745200 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Leo Augillare
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 16 consists of two structures; a suburban ranch and a mobile home; both stand on concrete blocks. The ranch is sheathed with aluminum siding; window frames are typically aluminum. The roof is a front gable, there is an attached gable at the front. The roof is seal tab.



Condition of the Building

Excellent
Length—front-back
65'6" feet
Width—side-side
24'7" feet
Orientation—bearing from
Front East
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #12

View from the Northeast



View from the Southeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1952
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 2
Frame Number(s): 8, 9
Location of Negative: R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 13
Parish: St. Charles
Address: 1756 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321720 N 745200 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Melvin Brown
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 13 is a bungalow which is raised on concrete block piers. The sides are sheathed with asphalt shingles; window frames are wooden an double hung. wooden and double hung. The roof is a front gable with an attached gable porch at the front; a soffit is present at the eaves. Also on site is a carport, doghouse, and gardens.



Condition of the Building

Excellent
Length--front-back
43'7" feet
Width--side-side
34'4" feet
Orientation--bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #13

View from the Southwest



View from the East



1c HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 2

Frame Number(s): 11, 12

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 14

Parish: St. Charles

Address: 1728 Union Lane

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321700 N 745200 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Artie Smith

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 14 is a bungalow which is raised on concrete block piers. The sides are sheathed with 6" lapped weatherboards; aluminum window frames are present as well as jalouise windows. The roof is a rear gable with a hipped front and gable attachments over the porch and entry; a vented soffit is present.



Condition of the Building

Excellent

Length—front-back

56'0" feet

Width—side-side

24'3" feet

Orientation—bearing from

Front East

Roof inclination

degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconnerie () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierrie () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #14

View from the Northeast



Shed to the North



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information
Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle
Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 2
Frame Number(s): 13, 14
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information
Parish Number: _____ Site: Montz 15
Parish: St. Charles
Address: 1726 Union Lane
Montz, LA
Topographic Quadrangle
Name: LaPlace
Size: 1:24,000
UTM 3321700 N 745180 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information
Resident: _____
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession
First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property: _____
Architectural and historical significance: Site 15 was originally a shotgun but has seen extensive renovations; it rests on pre-fabricated concrete piers. The sides are sheathed with lapped, wooden weatherboards; window frames are both wooden and aluminum. The roof is hipped and has several attachments; it is sheathed in tin. The core of this house is very old.



Condition of the Building
Good
Length—front-back
41'0" feet
Width—side-side
26'6" feet
Orientation—bearing from
Front East
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

Documents seen by you and bearing on the structure:

Title

Date Location

Experts who advised you specifically on this structure:

Name and Address

Name and Address

Published works that bear on your judgement:

Author: _____
Date: _____
Title: _____
Publisher: _____
City: _____

Author: _____
Date: _____
Title: _____
Publisher: _____
City: _____

Historic function of principal building: (☒) residential () religious
() social () commercial () industrial () governmental
() agricultural () other _____

Historic structures (dependencies) present on the same site: () store
() kitchen () quarters () garconierre () office () barn
() corncrib () smokehouse () shed () privy () cistern
() fence () wall () well () machinery () cemetery
() notable garden () pigeonierre () gazebo () statuary () mill
() garage () commissary () other _____

Montz #15

View from the Northeast



View from the Southeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1983
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 2
Frame Number(s): 15, 16, 17
Location of Negative: R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 16
Parish: St. Charles
Address: 1760 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321700 N 745180 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information


Resident: Robert Eugene
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 16 is very modern suburban ranch type which is constructed on a concrete slab. The sides are sheathed with grooved exterior plywood; all window frames are aluminum. The roof is a long low front gable with seal tab shingles. Mr. Eugene's house is the most recent house in Montz as well as the largest.



Condition of the Building

Excellent
Length—front-back
67'9" feet
Width—side-side
43'2" feet
Orientation—bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Historic function of principal building: (☒) residential () religious

() social () commercial () industrial () governmental

() agricultural () other _____

Historic structures (dependencies) present on the same site: () store

() kitchen () quarters () garconierre () office () barn

() corncrib () smokehouse () shed () privy () cistern


() fence () wall () well () machinery () cemetery

() notable garden () pigeonierre () gazebo () statuary () mill

() garage () commissary () other _____

Montz #16

View from the East



View from the Northeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 2

Frame Number(s): 18, 19

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 17

Parish: St. Charles

Address: 1724 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321700 N 745200 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 17 is a cabin type which stands on concrete block piers. The sides are sheathed with beveled and lapped wooden weather boards; both aluminum and wooden windows are present. The roof is a side gable with exposed rafters at the eaves. An old fence is also present on the site.



Condition of the Building

Poor

Length—front-back

26'3" feet

Width—side-side

20'4" feet

Orientation—bearing from

Front East

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #17

View from the Southeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 2
Frame Number(s): 34, 35, 36
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 18
Parish: St. Charles
Address: 1722 Union
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321660 N 745200 E
Sect. 11 T 12s R 7E
Remarks: Not Eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Norma Williams
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 18 is the old Montz schoolhouse; now used as a rental property. The building is constructed on brick piers. Lapped, cypress weatherboards are present beneath modern asphalt shingles on the sides; all windows are wood six over six and original. The roof is a side gable with an attached gable porch on the front; rafters are exposed and brackets are present at the gable ends.—The roof-is-slate.



Condition of the Building

Good _____
Length—front-back _____
40'0" feet
Width—side-side _____
29'4" feet
Orientation—bearing from _____
Front East
Roof inclination _____
degree _____
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: () residential () religious
 () social () commercial () industrial (X) governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (X) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #18

View from the Southeast



View from the East



Montz #18

Gable over porch at front



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1975
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 3

Frame Number(s): 1, 2, 3

Location of Negative: R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 19

Parish: St. Charles

Address: _____

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321660 N 745200 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property: Providence Baptist Church

Architectural and historical significance: The church was constructed on this site in 1975. Built on a slab, the walls of the church are concrete block and have aluminum window and door frames. The roof is a combination of side gable and hipped; a soffit is present and seal tab shingles are used. A small gable extension over the entrance supports a steeple.



Condition of the Building

Excellent

Length—front-back

63'0" feet

Width—side-side

56'8" feet

Orientation—bearing from

Front West

Roof inclination

_____ degree

Operator: _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: () residential (X) religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #19

View from the Northwest



View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 3

Frame Number(s): 20

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 20

Parish: St. Charles

Address: 1721 Union Lane

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321640 N 745220 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Gary Johnson

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 20 is a mobile home raised on concrete blocks and shinned with wood; a corrugated metal skirt is at the base. This trailer is entered from the southern side. Mr. Johnson rents this trailer.



Condition of the Building

Good

Length—front-back

56'0" feet

Width—side-side

11'8" feet

Orientation—bearing from

Front East

Roof Inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #20

View from the Northeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1975
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 3
Frame Number(s): 4, 5, 6
Location of Negative:
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 21
Parish: St. Charles
Address: 1700 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321640 N 745200 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information


Resident: Leon Mason
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 21 is a mobile home raised on concrete blocks and shimmed with wood. Pre-fabricated concrete steps lead to the northern entrance. This trailer has been on site for eight years.



Condition of the Building

Good _____
Length—front-back
64'0" feet
Width—side-side
13'9" feet
Orientation—bearing from
Front East
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

Documents seen by you and bearing on the structure:

Title

Date Location

Experts who advised you specifically on this structure:

Name and Address

Name and Address

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____


City: _____

Historic function of principal building: (☒) residential () religious
() social () commercial () industrial () governmental
() agricultural () other _____

Historic structures (dependencies) present on the same site: () store
() kitchen () quarters () garconierre () office () barn
() corncrib () smokehouse () shed () privy () cistern
() fence () wall () well () machinery () cemetery
() notable garden () pigeonierre () gazebo () statuary () mill
() garage () commissary () other _____

Montz #21

View from the East



View from the Northeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 3

Frame Number(s): 10, 11, 12

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 22

Parish: St. Charles

Address: _____

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321640 N 745200 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Blain Mason

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 22 is a mobile home raised on concrete blocks and shimmed with wood. The trailer is entered on the northern side; steps are metals. There is a a/c window unit on the northern side as well.



Condition of the Building

Good

Length—front-back

67'6" feet

Width—side-side

13'9" feet

Orientation—bearing from

Front East

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

Documents seen by you and bearing on the structure:

Title

Date Location

Experts who advised you specifically on this structure:

Name and Address

Name and Address

Published works that bear on your judgement:

Author: _____
Date: _____
Title: _____
Publisher: _____
City: _____


Author: _____
Date: _____
Title: _____
Publisher: _____
City: _____

Historic function of principal building: (X) residential () religious
() social () commercial () industrial () governmental
() agricultural () other _____


Historic structures (dependencies) present on the same site: () store
() kitchen () quarters () garconierre () office () barn
() corncrib () smokehouse () shed () privy () cistern
() fence () wall () well () machinery () cemetery
() notable garden () pigeonierre () gazebo () statuary () mill
() garage () commissary () other _____

Montz #22

View from the East



View from the Northeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 3
Frame Number(s): 7, 8, 9
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 23
Parish: St. Charles
Address: 1724 Union
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321600 N 745220 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Mrs. P. Taylor
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 23 is a suburban ranch raised on concrete block piers. The walls are sheathed with lapped masonite weatherboards; all window frames are aluminum. The roof is a side gable with a front gable attached over the entrance. A porch is present at the front.



Condition of the Building

Good
Length—front-back
32'2" feet
Width—side-side
30'1" feet
Orientation—bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #23

View from the East



View from the Southwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 3

Frame Number(s): 23, 24, 25

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 24

Parish: St. Charles

Address: 1724 Union

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321580 N 745160 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____


Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 24 is a moilbe home trailer raised on concrete blocks and shimmed with wood. A corrugated metal skirt is present at the base. A porch is located in front of the entrance; an additional entrance is present at the rear.



Condition of the Building

Fair

Length—front-back

60'0" feet

Width—side-side

11'10" feet

Orientation—bearing from

Front West

Roof inclination

degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Historic function of principal building: (☒) residential () religious

() social () commercial () industrial () governmental

() agricultural () other _____

Historic structures (dependencies) present on the same site: () store

() kitchen () quarters () garconierre () office () barn

() corncrib () smokehouse () shed () privy () cistern

() fence () wall () well () machinery () cemetery

() notable garden () pigeonierre () gazebo () statuary () mill

() garage () commissary () other _____

Montz #24

View from the Southwest



View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information
Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 3
Frame Number(s): 26, 27, 28
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information
Parish Number: _____ Site: Montz 25
Parish: St. Charles
Address: 1725 Union Lane
Montz, LA

Topographic Quadrangle
Name: LaPlace
Size: 1:24,000
UTM 3321500 N 745150 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information
Resident: _____
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession
First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property: _____
Architectural and historical significance: Site 25 is a creole cabin raised on brick piers; probably one of the oldest structures in Montz. Lapped cypress boards have been covered with asphalt shingles; aluminum and wooden windows are present. The roof is a side gable with an attached shed and gable at the rear. Rafters are exposed, the roof is tin. House has little historical integrity.



Condition of the Building
Poor
Length—front-back
46'3" feet
Width—side-side
31'10" feet
Orientation—bearing from
Front South
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #25

View from the Northwest



View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1972
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 3
Frame Number(s): 29, 30, 31
Location of Negative:
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 26
Parish: St. Charles
Address: 1700 Union Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321500 N 745160 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Leroy Mason
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 26 is a suburban ranch constructed on a slab. The sides are sheathed with brick veneer; all window frames are aluminum. The roof is hipped and a vented soffit is present at the eaves; seal tab roof. There is a shed to the west of the house.



Condition of the Building

Good _____
Length—front-back
65'0" feet
Width—side-side
34'0" feet
Orientation—bearing from
Front East
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____


City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (☒) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #26

View from the Northeast



View from the Southeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 4

Frame Number(s): 8, 9, 10

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 27

Parish: St. Charles

Address: _____

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321480 N 745200 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____


Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 27 is the Montz Tavern which is located at the corner of River Road and Kenner Lane; the structure stands on brick piers. The sides are sheathed with 6" lapped weatherboards. The roof is a front gable; a parapet wall at the front screens the roof. There is evidence of signage on the structure.



Condition of the Building

Poor

Length--front-back

40'2" feet

Width--side-side

32'0" feet

Orientation--bearing from

Front South

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: () residential () religious
 () social (X) commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #27

View from the Southeast



View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 3
Frame Number(s): 32, 33, 34
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 28
Parish: St. Charles
Address: 726 Tower Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321500 N 745200 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Evelyn Richards
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 28 is a bungalow type raised on brick piers. The sides are sheathed with lapped, 6" wooden weatherboards; both wood and aluminum framed windows are present. The roof is hipped and exposed rafters are at eaves; there is a tin roof. There is a carport to the north of the house.



Condition of the Building

Good

Length—front-back
62'0" feet

Width—side-side
28'0" feet

Orientation—bearing from
Front South

Roof inclination
_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

Documents seen by you and bearing on the structure:

Title

Date Location

Experts who advised you specifically on this structure:

Name and Address

Name and Address

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Historic function of principal building: (☒) residential () religious
() social () commercial () industrial () governmental
() agricultural () other _____

Historic structures (dependencies) present on the same site: () store
() kitchen () quarters () garconierre () office () barn
() corncrib () smokehouse (☒) shed () privy () cistern
() fence () wall () well () machinery () cemetery
() notable garden () pigeonierre () gazebo () statuary () mill
() garage () commissary () other _____

Montz #28

View from the West



View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information
Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 4
Frame Number(s): 1, 2, 3
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information
Parish Number: _____ Site: Montz 29
Parish: St. Charles
Address: 726 Tower
Montz, LA

Topographic Quadrangle
Name: LaPlace
Size: 1:24,000
UTM 3321520 N 745220 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information
Resident: Winslow Parquet
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession
First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property: _____
Architectural and historical significance: Site 59 is a bungalow type which is raised on concrete blocks. The walls are sheathed with lapped wooden weatherboards; all window frames are aluminum. The roof is hipped and there is a combination gable and shed roof addition at the rear.



Condition of the Building
Good
Length—front-back
54'0" feet
Width—side-side
28'3" feet
Orientation—bearing from
Front South
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #29

View from the West



View from the North



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 3
Frame Number(s): 5, 6, 7
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 30
Parish: St. Charles
Address: 726 B Tower
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321540 N 745240 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: _____
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property: Montz Sweet Shop

Architectural and historical significance: Site 30 is a side gable cabin type raised on concrete block piers. The sides are sheathed with beveled and lapped 8" weatherboards; all windows are aluminum framed. The roof is a side gable with a soffit at the front and exposed rafters at the rear. Asphalt shingles are on the roof.



Condition of the Building

Poor _____
Length—front-back _____
24'2" feet
Width—side-side _____
10'2" feet
Orientation—bearing from _____
Front West
Roof inclination _____
degree _____
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

Documents seen by you and bearing on the structure:

Title

Date Location

Experts who advised you specifically on this structure:

Name and Address

Name and Address

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Historic function of principal building: () residential () religious
() social (X) commercial () industrial () governmental
() agricultural () other _____

Historic structures (dependencies) present on the same site: () store
() kitchen () quarters () garconierre () office () barn
() corncrib () smokehouse () shed () privy () cistern
() fence () wall () well () machinery () cemetery
() notable garden () pigeonierre () gazebo () statuary () mill
() garage () commissary () other _____

AD-A170 796

CULTURAL RESOURCES INVENTORY OF THE MONTZ FRESHWATER
DIVERSION PROJECT CO. (U) GOODWIN (R CHRISTOPHER) AND
ASSOCIATES INC NEW ORLEANS LA H A FRANKS ET AL.


2/3


UNCLASSIFIED

23 JUN 86 COELMN/PD-86-06-UOL-2

F/G 5/6

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

Montz #30

View from the Southwest



View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 4
Frame Number(s): 11, 12, 13
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 31
Parish: St. Charles
Address: _____
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321540 N 745240 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Zachary Richards
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 31 consists of two structures; a shotgun and a steel garage. The shotgun is constructed on brick piers. The walls are sheathed with asphalt shingles; this cabin is very old and has been abandoned for six years. The shed roofed garage is used as an auto shop and has been here for nine years.



Condition of the Building

Poor

Length—front-back
28'2" feet

Width—side-side
27'5" feet

Orientation—bearing from
Front West

Roof inclination
_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social (☒) commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #31

View from the West



View from the Southwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information
Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle
Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 4
Frame Number(s): 14, 15, 16
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information
Parish Number: _____ Site: Montz 32
Parish: St. Charles
Address: _____
Montz, LA
Topographic Quadrangle
Name: LaPlace
Size: 1:24,000
UTM 3321560 N 745270 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information
Resident: _____
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession
First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property: _____
Architectural and historical significance: Site 32 is a shotgun raised on brick pillars. The sides are sheathed with beveled, lapped wooden weatherboards; window frames are wooden two over two. The roof is a front gable with a hipped porch at the front and an attached shed at the rear. The porch at the front has beaded boards on the ceiling.



Condition of the Building
Poor
Length—front-back
48'0" feet
Width—side-side
12'3" feet
Orientation—bearing from
Front South
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #32

View from the West



View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1929
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 4
Frame Number(s): 17, 18, 19
Location of Negative:
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 33
Parish: St. Charles
Address: 726 Tower Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321600 N 745280 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Maybel Rainey
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 33 is a bungalow type constructed on concrete block and pre-fab concrete piers. The sides are sheathed with 4" weather-boards which are not lapped; window frames are wooden six over six. The roof is a side gable with a front gable over the porch and front entrance; exposed rafters are present at the eaves. A shed roofed addition is present at the northern side.



Condition of the Building

Fair
Length—front-back
49'7" feet
Width—side-side
26'5" feet
Orientation—bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (☒) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #33

View from the Northwest



View from the Southwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 4

Frame Number(s): 20, 21, 22

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 34

Parish: St. Charles

Address: 726 Tower Lane

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321620 N 745280 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Rosemae Geason

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 34 is a double crib cabin type raised on concrete block piers. The sides are sheathed with beveled, lapped 8" weatherboards; all window frames are aluminum. The roof is a side gable with an attached gable over the entrance; a soffit is present at the eaves. The roof is sheathed with asphalt shingles.



Condition of the Building

Good

Length—front-back

31'2" feet

Width—side-side

22'3" feet

Orientation—bearing from

Front West

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #34

View from the Northwest



View from the Northeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: ca. 1960
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 4

Frame Number(s): 23, 24, 25

Location of Negative:

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 35

Parish: St. Charles

Address: 726 N. Tower Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321640 N 745280 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Villanese Braunfield

Ownership Information:

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 35 is a double pen cabin whis is raised on concrete block piers. The sides are sheathed with vinyl siding; all window frames are aluminum. The roof is a side gable with a gabled attachment placed north of the entrance; a shed roof addition is present at the read. There is a driveway at the southern side.



Condition of the Building

Fair

Length—front-back

34'4" feet

Width—side-side

26'5" feet

Orientation—bearing from

Front West

Roof inclination

degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #35

View from the West



View from the Southeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1978
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 4

Frame Number(s): 26, 27, 28

Location of Negative:

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 36

Parish: St. Charles

Address: 726 O Tower Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321680 N 745300 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Martha Nicholson

Ownership Information:

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____


Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 36 is a mobile home which stands on concrete blocks and is shinned with wood. Two entrances are accessed by wooden steps. Stones have been placed at the edge of the road. The trailer has been on this site for eight years.



Condition of the Building

Good

Length—front-back

56'0" feet

Width—side-side

11'9" feet

Orientation—bearing from

Front West

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #36

View from the West



View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger
Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 4
Frame Number(s): 29, 30
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 37
Parish: St. Charles
Address: 726 P Tower Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321720 N 745310 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Melvin Richards
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 37 is a suburban ranch type which is constructed on concrete block piers. The sides are brick veneer which extends to the ground and is vented at the base; all window frames are aluminum. The roof is hipped and a vented soffit is present at the eaves; the roof is sheathed with seal tab shingles. There is an arched entry at the front. A shed is placed to the north.



Condition of the Building

Good
Length—front-back
60'10" feet
Width—side-side
31'2" feet
Orientation—bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

Documents seen by you and bearing on the structure:

Title

Date Location

Experts who advised you specifically on this structure:

Name and Address

Name and Address

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____


City: _____

Historic function of principal building: (☒) residential () religious
() social () commercial () industrial () governmental
() agricultural () other _____

Historic structures (dependencies) present on the same site: () store
() kitchen () quarters () garconierre () office () barn
() corncrib () smokehouse (☒) shed () privy () cistern
() fence () wall () well () machinery () cemetery
() notable garden () pigeonierre () gazebo () statuary () mill
() garage () commissary () other _____

Montz #37

View from the Southwest



View from the Southeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1978
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 4

Frame Number(s): 31, 32, 33, 34

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 38

Parish: St. Charles

Address: 726 P Tower

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321740 N 745310 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 38 is a mobile home supported by concrete blocks and shinned with wood. Entrances on the north and south are both accessed by steel steps. A driveway is present at the north side. The trailer has been on the site for eight years.



Condition of the Building

Good

Length—front-back

52'0" feet

Width—side-side

11'9" feet

Orientation—bearing from

Front West

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #38

View from the West



View from the Southwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 5
Frame Number(s): 1, 2, 3
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 39
Parish: St. Charles
Address: 726 Q Tower
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321750 N 745320 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: _____
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 39 is a double pen cabin raised on concrete blocks. The walls are sheathed with vertically grooved exterior plywood; all window frames are aluminum. The roof is a side gable with an attached shed at the front which covers a continuous gallery; an attached gable is placed to the north of entrance. Soffits are present at the eaves. The roof above the gallery is supported

of the house.

Condition of the Building

Fair

Length—front-back

47'0" feet

Width—side-side

28'4" feet

Orientation—bearing from

Front West

Roof inclination

_____ degree

Operator _____



Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () wall () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #39

View from the Northwest



View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1979
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 5

Frame Number(s): 4, 5

Location of Negative: R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 40

Parish: St. Charles

Address: 726 RR Tower Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321800 N 745330 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Joe Smith, Jr.

Ownership Information:

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 40 is a mobile home raised on concrete blocks and shinned with wood. Wooden steps lead to the front entrance; a small porch is present at the rear of the structure. There is a small shell lot in front of the trailer where cars are parked. Mr. Smith stated that this is the first structure to occupy this site.



Condition of the Building

Good _____

Length—front-back _____

60'0" _____ feet

Width—side-side _____

11'9" _____ feet

Orientation—bearing from _____

Front West _____

Roof inclination _____

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonnier () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #40

View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 5

Frame Number(s): 6, 7

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 41

Parish: St. Charles

Address: 726 R Tower Lane

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321840 N 745340 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Mr. Noble

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 41 is a bungalow type which stands on concrete block piers. The sides are sheathed with 6" lapped, wooden weatherboards; jalouise and wooden two over two windows are present. The roof is primarily a front gable with two gabled attachments over a screened porch and the primary entrance; a vented soffit is present at the eaves. The roof is sheathed with slate.



Condition of the Building

Good

Length—front-back

51'7" feet

Width—side-side

24'3" feet

Orientation—bearing from

Front West

Roof inclination

degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconnerie () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierie () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #41

View from the Southwest



View from the Southeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 5

Frame Number(s): 8, 9, 10

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 42

Parish: St. Charles

Address: 101 Kenner Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321460 N 745300 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 42 is a composite cabin and bungalow type which is raised on pre-fabricated concrete pillars. The sides are sheathed with 8" beveled, lapped wooden weatherboards; all window frames are aluminum. The roof is a front gable sheathed with various sized boards and tin; a gabled addition has been added at the northern side. Also on the site are a shed, grape arbor, and a garden.



Condition of the Building

Good

Length—front-back

48'0" feet

Width—side-side

29'0" feet

Orientation—bearing from

Front South

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (☒) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #42

View from the Northeast



View from the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 5

Frame Number(s): 11, 12, 13

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 43

Parish: St. Charles

Address: _____

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321480 N 745280 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____


Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 43 is a mobile home (the largest inventoried in Montz) leveled with jacks placed on concrete pads. Steel steps lead to a centrally located front door. Pens constructed of various materials are present behind this structure' a large cypress post is placed at the road which may have supported a mailbox at some time.



Condition of the Building

Good

Length—front—back

76'0" feet

Width—side—side

13'9" feet

Orientation—bearing from

Front East

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary (☒) other pens

Montz #43

View from the Northwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1973
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 5

Frame Number(s): 14, 15, 16

Location of Negative:

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 44

Parish: St. Charles

Address: 116 Kenner Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321480 N 745290 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: Arthur Harrison

Ownership Information:

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 44 is a mobile home which has been on this site for thirteen years; it is raised on concrete blocks and shimmed with wood.

A plywood deck is present at the front entrance. Also on site are a carport and shed.

A large grass lot is present south of the house.



Condition of the Building

Good

Length—front-back

66'0" feet

Width—side-side

13'9" feet

Orientation—bearing from

Front West

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (X) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #44

View from the South



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 5
Frame Number(s): 17, 18, 19
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 45
Parish: St. Charles
Address: 131 Kenner Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321500 N 745300 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Clara Parquet
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 45 is a bungalow type raised on concrete block piers. The sides are sheathed with 6" lapped, wooden weatherboards; windows are wooden six over six. The roof is a front gable with an extension at the front covering a porch; exposed rafters are present at the eaves. The roof is sheathed with asphalt shingles. A large vacant lot is fenced at the southern side.



Condition of the Building

Poor _____
Length—front-back _____
37'0" feet
Width—side-side _____
24'0" feet
Orientation—bearing from _____
Front East _____
Roof inclination _____
degree _____
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #45

View from the South



View from the Southwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1954
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 5
Frame Number(s): 23, 24, 25
Location of Negative: R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 46
Parish: St. Charles
Address: 133 Kenner Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321540 N 745290 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: _____
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 46 is a bungalow type (a corrugated steel skirt at the base made identification of foundation type impossible). The walls are sheathed with 8" lapped, wooden weatherboards. The roof is hipped with a similarly hipped attachment over the entrance; a vented soffit is present at the east and west eaves. There are two sheds behind this house; one is modern; the other is very old.



Fair
Length—front-back
59'0" feet
Width—side-side
24'0" feet
Orientation—bearing from
Front East
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address	Age	Reason for Knowing the Facts
_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title	Date	Location
_____	_____	_____
_____	_____	_____
_____	_____	_____

Experts who advised you specifically on this structure:

Name and Address	Name and Address
_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____


Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (☒) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #46

View from the North



View from the Northeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1966
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 5
Frame Number(s): 26, 27
Location of Negative:
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 47
Parish: St. Charles
Address: 132 Kenner Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321560 N 745290 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Myrtle Creecy Seymore
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 47 is a cabin type raised on concrete block piers. The walls are sheathed with vinyl siding; all window frames are aluminum. The roof is a side gable with soffits ((wooden) at the east and west eaves; the roof is sheathed with tin. There is a porch present at the western facade which is supported by 3" x 3" wooden posts. A carport and shed are also present.



Condition of the Building

Good
Length—front-back
38'6" feet
Width—side-side
27'4" feet
Orientation—bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (☒) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #47

View from the Southwest



View from the Southeast



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: 1952
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 5
Frame Number(s): 28, 29, 30
Location of Negative:
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 48
Parish: St. Charles
Address: 136 Kenner Lane
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321570 N 745320 E
Sect. 11 T 12S R 1E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: Martin Richards
Ownership Information:
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 48 is a cabin type raised on concrete block piers. Walls are sheathed with beveled and lapped 1" X8" wooden weatherboards; windows frames are a combination of both wooden and aluminum. The roof is a side gable with an addition at the rear (the gable here faces east); soffits are present at the eaves. An attached gable extends over the front entrance. Livestock (chickens, goats, turkeys) pens are located to the east of the house.



Condition of the Building

Poor
Length—front-back
42'4" feet
Width—side-side
36'3" feet
Orientation—bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse (☒) shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary (☒) other pens

Montz #48

View from the Northwest



Pens to the East



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information
Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 5
Frame Number(s): 31 32, 33
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information
Parish Number: _____ Site: Montz 49
Parish: St. Charles
Address: _____
Montz, LA

Topographic Quadrangle
Name: LaPlace
Size: 1:24,000
UTM 3321570 N 745320 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information
Resident: _____
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession
First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property: _____
Architectural and historical significance: Site 49 is a cabin type which is constructed on brick piers. The sides are sheathed with 8" lapped wooden weatherboards; windows are wooden six over six. The roof is a side gable with an attached gable over the entrance; soffits are present at the eaves but are not vented. Asphalt shingles are in use on the roof.



Condition of the Building
Poor
Length—front-back
39'6" feet
Width—side-side
24'6" feet
Orientation—bearing from
Front West
Roof inclination
_____ degree
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Author: _____

Date: _____

Title: _____

Publisher: _____

City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #49

View from the Northeast



View from the North



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986
Film Type: Plus-X-Pan
Roll Number: 5
Frame Number(s): 34, 35, 36
Location of Negative: _____
R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 50
Parish: St. Charles
Address: _____
Montz, LA

Topographic Quadrangle

Name: LaPlace
Size: 1:24,000
UTM 3321570 N 745290 E
Sect. 11 T 12S R 7E
Remarks: Not eligible for Nat'l Register
National Register Status: Not listed

Social Information

Resident: _____
Ownership Information: _____
Name: _____
Address: _____
Town: _____
Phone: _____

Succession

First Owner _____
Years _____
Second Owner _____
Years _____
Third Owner _____
Years _____

Historic Name of the Property:

Architectural and historical significance: Site 50 is a mobile home or trailer raised on concrete block piers and shimmed with wood. There is a slab present at the entrance with a ramp leading to it (the resident is disabled). A satellite dish is placed at the northwest corner of the site.



Condition of the Building

Good _____
Length—front-back _____
67'0" feet
Width—side-side _____
13'6" feet
Orientation—bearing from _____
Front East
Roof inclination _____
degree _____
Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (☒) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #50

View from the Southwest



HISTORIC STANDING STRUCTURE SURVEY

Division of Historic Preservation
Post Office Box 44247 * Baton Rouge, LA 70804 * 504-342-6682

Survey Information

Date of Construction: _____
Surveyor in Charge: Jeff Treffinger

Others in Team: Don Bascle

Date of Survey: March 5, 6, 7, 1986

Film Type: Plus-X-Pan

Roll Number: 6

Frame Number(s): 1, 2, 3

Location of Negative: _____

R. Christopher Goodwin & Assoc., Inc.

Location Information

Parish Number: _____ Site: Montz 51

Parish: St. Charles

Address: 152 Kenner Lane

Montz, LA

Topographic Quadrangle

Name: LaPlace

Size: 1:24,000

UTM 3321580 N 745300 E

Sect. 11 T 12S R 7E

Remarks: Not eligible for Nat'l Register

National Register Status: Not listed

Social Information

Resident: _____

Ownership Information: _____

Name: _____

Address: _____

Town: _____

Phone: _____

Succession

First Owner _____

Years _____

Second Owner _____

Years _____

Third Owner _____

Years _____

Historic Name of the Property:

Architectural and historical significance: Site 51 is a cabin type raised on concrete block piers. The structure is sheathed with 1" x 8" beveled and lapped wooden siding; all windows frames are aluminum. The roof is a side gable with an attached gable extending over the entrance; this extension is supported by wrought iron pillars. An unvented soffit is present at the east and west eaves.



Condition of the Building

Poor

Length—front-back

32'6" feet

Width—side-side

24'6" feet

Orientation—bearing from

Front West

Roof inclination

_____ degree

Operator _____

Include here the sources of the information that you used in preparing your report on this structure.

Persons who told you the facts about the structure:

Name and Address

Age

Reason for Knowing the Facts

_____	_____	_____
_____	_____	_____
_____	_____	_____

Documents seen by you and bearing on the structure:

Title

Date Location

_____	_____
_____	_____
_____	_____

Experts who advised you specifically on this structure:

Name and Address

Name and Address

_____	_____
_____	_____
_____	_____

Published works that bear on your judgement:

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Author: _____
 Date: _____
 Title: _____
 Publisher: _____
 City: _____

Historic function of principal building: (X) residential () religious
 () social () commercial () industrial () governmental
 () agricultural () other _____

Historic structures (dependencies) present on the same site: () store
 () kitchen () quarters () garconierre () office () barn
 () corncrib () smokehouse () shed () privy () cistern
 () fence () wall () well () machinery () cemetery
 () notable garden () pigeonierre () gazebo () statuary () mill
 () garage () commissary () other _____

Montz #51

View from the South



View from the Southeast

